



Photo 1 – View of airplane on a snowbank with dual propeller strike damage (courtesy of the owner)