



Photo 1 – View of damage to vertical stabilizer (photo courtesy of the FAA)