



Photo 1 – View of damaged fuselage (courtesy of the FAA)



Photo 2 - View of damaged tailcone and horizontal stabilizer (courtesy of the FAA)