



Photo 1 – View of left wing and vertical stabilizer damage (Photo courtesy of the FAA)



Photo 2 – View of right wing and lift strut damage (Photo courtesy of the FAA)