



Photo 1 – View of damage to the structural hat on the belly of the airplane (Courtesy of FAA)