



Photo 1 – View of damage to the right wing lift strut (Courtesy of FAA)