



Photo 1 – View of damaged right horizontal stabilizer (Photo courtesy of the pilot)



Photo 2 – View of separated right elevator (Photo courtesy of the pilot)