



Photo 1 – View of left-wing rib and stringers damage (courtesy of the FAA)