

STAR MARIANAS AIR, INC.

TINIAN, MP 96952

ADVERSE EVENTS REPORT FORM

Rec'd 042019
0945H R

DATE OF EVENT:

ORIGINATOR:

- ☐ MAINTENANCE
☐ FLIGHT
☒ MAINTENANCE/FLIGHT
☐ STATIONS

- ☐ RAMP
☐ OTHER, SPECIFY _____

ISLAND:

- ☒ SAIPAN
☐ TINIAN
☐ ROTA
☐ GUAM

DESCRIBE THE ADVERSE EVENT:

* IF A/C RELATED, PLEASE PROVIDE TAIL # 4599X & ATA CHAPTER _____

4/19/19 18:30

Took off Saipan Station with 3 passengers. When reached the cruising altitude of 1500', something popped open in the cowl area and a partial cowl was shaking near the propeller. Found out the engine was still running, so

ACTION PERFORMED/CORRECTED? IF YES, DESCRIBE BELOW

declared emergency and returned back to runway 7 at PG&SN.

① Who is the pilot? Sung.

--- END ---

-- FORWARD TO SAFETY COMMITTEE --

TRACKING NO.

SAFETY RISK
INDEX CODE:

PROBABILITY:

- 5 - FREQUENT
4 - OCCASIONAL
3 - REMOTE
2 - IMPROBABLE
1 - EXTREMELY
IMPROBABLE

SEVERITY:

- A - CATASTROPHIC
B - HAZARDOUS
C - MAJOR
D - MINOR
E - NEGLIGIBLE

FOLLOW-UP

TYPE(S):
(CIRCLE ALL THAT
APPLY)

- RED DOT ITEM
- TRACK - SEE
PAGE 2
- DISCUSS - SEE
PAGE 2
- RE-TRAIN - SEE
PAGE 2
- NOT REQUIRED
- CLOSED

DATE CLOSED:

NOTES:

09.22