



Photo 1 – View of damaged right wing lift strut (Photo courtesy of the FAA)