



Photo 1 – View of vertical stabilizer damage (photo courtesy of the FAA)