



RECORD OF MEMORANDUM

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 6/24/2019
Person Contacted: Jack Walker (pilot)
NTSB Accident Number: GAA19CA336

Narrative:

The following is a synopsis of the information provided by the pilot on this date:

- The airplane was on approach to Ontario airport for a final stop when the engine lost power.
- The pilot unsuccessfully attempted to restart the engine and to land on the runway, but airplane impacted the perimeter fence, about 75 yards from the end of the runway.
- The pilot sustained minor injuries.
- The pilot reported there were no preaccident mechanical failures or malfunctions that would have precluded normal operations.
- A post-accident examination by the FAA inspector revealed that there was no fuel in the system and that the pilot had ran the engine dry.