



RECORD OF CONVERSATION

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 7/10/2019
Person Contacted: Richard Ortenheim (Operator)
NTSB Accident Number: GAA19CA390

Narrative:

The following is a synopsis of the information provided by the operator on this date:

The operator reported that during the solo student pilot's landing, the airplane immediately veered left, exited the runway and the left wing struck a paving vehicle on the adjacent taxiway.

The airplane sustained substantial damage to the left wing.

The operator reported that there was no preimpact mechanical malfunctions or failures that would have precluded normal operations.