



Photo 1 – View of inverted airplane and damaged empennage (Photo courtesy of the pilot)




Photo 2 – View of partially engaged parking brake (Photo courtesy of the pilot)