



Photo 1 – View of helicopter damage to the main rotor system, fuselage, tailboom, and tail rotor system (courtesy of the FAA)



Photo 2 – View of right side tail rotor control pedals (courtesy of the FAA)