





Photo 1 – View of tail rotor gear box damage (photo courtesy of the operator)



Damage marks in valleys of gears

Photo 2 - View of tail rotor gear box damage (photo courtesy of the operator)