



Photo 1 – View of nosed over airplane with damage to left wing lift strut (courtesy of the FAA)