



**Photo 1 – View of damaged left stabilator (Photo courtesy of the FAA)**



**Photo 2 – View of damaged empennage (Photo courtesy of the FAA)**