



## **RECORD OF E-MAIL CORRESPONDENCE**

**Eric M. Gutierrez**  
**Aviation Accident Investigator**  
**General Aviation Accident Division**

---

**Date: September 3, 2019**  
**Person Contacted: Michael W. Matthews (FAA)**  
**NTSB Accident Number: GAA19CA520**

---

### **Narrative:**

The following is a synopsis of the information provided by Mr. Matthews in a e-mail correspondence.

On September 2, 2019, at about 12:05 LCL, N31934 was landing at Mackinac Island. During landing flare on runway 26, aircraft experienced a sudden crosswind and drifted to the left. Aircraft bounced on touchdown and further drifted to left leaving the runway surface striking a runway light, through a ditch, then coming to rest in the grass. From photographs, right wing is damaged, all three landing gear are collapsed, sudden engine stoppage with prop damage. No injuries reported.