



Photo 1 – View of damaged right-wing lift strut and vertical stabilizer (courtesy of the pilot)