



Photo – View of damage to fuselage and float attachment point (Courtesy of the FAA)