



Photo 1 – View of damage to both wings and fuselage (photo courtesy of the FAA)



Photo 2 - View of damage to both wings and fuselage (photo courtesy of the FAA)



Photo 3 - View of selector valve lever on right fuel tank (photo courtesy of the FAA)