



RECORD OF CONVERSATION

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 10/24/2019
Person Contacted: Fred King (FAA Inspector)
NTSB Accident Number: GAA20CA028

Narrative:

The following is a synopsis of the information provided by the FAA Inspector in a telephone conversation:

The FAA inspector reported that the shortly after touchdown, the airplane veered left and impacted a ditch in the safety area adjacent the runway. The pilot reported to him that it was just pilot error and that there was nothing wrong mechanically with the airplane.