



RECORD OF CONVERSATION

Eleazar Nepomuceno
Air Safety Investigator
General Aviation Accident Division

Date: 11/14/2019
Person Contacted: Tamir Dashmyagmarjav
NTSB Accident Number: GAA20CA067

Narrative:

The following is a synopsis of the information provided by the student pilot in a telephone conversation on this date:

- Purpose of the flight was to practice pattern work
- Accident occurred during 5th landing
- Approach was good, airspeed slightly high about 70-75 knots
- Maintained centerline prior to touchdown
- Airplane touchdown hard slightly left of the runway centerline
- Airplane veered left, and he corrected with opposite aileron and rudder, but the airplane continued left, exited the runway to the left and struck taxiway signs
- Total flight hours: 72 hours; total flight hours in make and model: 30 hours
- There were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.