



Photo 1 – View of damage to the inboard right wing (Courtesy of FAA)



Photo 2 - View of damage to the inboard right wing (Courtesy of FAA)



Photo 3 – View of the left side canopy latch (Courtesy of FAA)



Photo 4 – View of the of the right side canopy handle and catch and lever (Courtesy of FAA)