



Bent longeron on
the left side of the
fuselage behind the
firewall

Photo 3. Bent Longeron Left Side (Provided by FAA)