



RECORD OF CONVERSATION

Dennis Hogenson
Air Safety Investigator
Western Pacific Region

Date: November 21, 2013
Person Contacted: Thomas Hillesland, Airworthiness Inspector, Helena FSDO
NTSB Accident Number: WPR12LA317

Today I contacted Mr. Thomas Hillesland (TH) of the Helena FSDO, regarding the accident that occurred in Bridger, MT. TH responded to the site shortly after the accident and performed the onsite portion of the investigation. TH reported that a postaccident examination of the airframe, engine and flight control system components revealed no evidence of a preimpact mechanical malfunction or failure.

END - djh