



RECORD OF CONVERSATION

Howard Plagens
Senior Air Safety Investigator
Western Pacific Region

Person Contacted: John Shaper, FAA Inspector Riverside FSDO
Date: 06-17-2014
Time: 0900
Subject: WPR14LA049; Firefly 10; N1623; Temecula, CA

Narrative:

The following information was provided by Inspector Shaper:

Pilot
DOB [REDACTED] 1943
ATP [REDACTED]
Total pilot time is 11,000
Time in make and model 1500
Last 90 days 75
Last year 120

No medical, medical was lost due to health issues, no medical required by rule on balloon operations.

Balloon was inspected on 09-04-2013 and an annual/100 hour inspection was accomplished at that time. The balloon had 443.0 at the time of the inspection and 482.2 when the accident occurred.