



Both propeller levers observed in the retarded position