



NTSB RECORD OF CONVERSATION

Investigator name: Lawrence Lewis
Mode: Aviation Position: Air Safety Investigator
Region: Western Pacific

Date: 9/9/2014
Person Contacted: Hal Heiden
Owner/Operator
Farm AG Enterprises LLC
Buckeye AZ
NTSB Accident Number: WPR14LA371

Narrative

Mr. Heiden was the owner/operator of Farm AG Enterprises LLC and was the contact and reporting party for the accident.

Mr. Heiden reported that following takeoff from his AG strip, N3097F lost power and the pilot landed straight ahead in a field. The airplane sustained substantial damage. He was awaiting arrival of the FAA air safety inspector.

Following the visit from the FAA inspector Mr. Heiden ceased communicating with the IIC, and did not return the completed NTSB Form 6120, (Owner/Operator Report of Accident/Incident) as requested by the IIC.

----- END -----

The digest was reviewed with him/her during the phone call and he/she agreed with the content.