

ACCIDENT NUMBER:

WPR15FA051

For Use In All Modal Investigations

REGISTERED OWNER (name and address) Native Range Capture Services Inc. [REDACTED]		IDENTIFICATION NUMBER N3234U	
		MAKE Robinson	
LOCATION North Salt Lake, UT	DATE OF ACCIDENT 12/2/14	MODEL R44 II	
RETAINED BY NTSB REPRESENTATIVE Andrew L. Swick		TITLE Aviation Accident Investigator	DATE 12/2/14
The National Transportation Safety Board has ☐ has not ☐ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released.			
☒ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE Andrew L. Swick		TITLE Aviation Accident Investigator	DATE 12/02/2014
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.)			
I HEREBY ACKNOWLEDGE:			
☒ Receipt of the above described wreckage.			
☐ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNOWLEDGEMENT Shari Thompson		TITLE Sr. Claims Rep	DATE 6/20/2016
ADDRESS [REDACTED]		PHONE NUMBER & EMAIL [REDACTED]	

REMARKS: