



RECORD OF CORRESPONDENCE

**Howard Plagens
Senior Air Safety Investigator
Western Pacific Region**

Person Contacted: Lori MacNichol – pilot’s mother

Date: 01-29-2016

Time: 0902

Subject: WPR15FA206; Piper PA22-135; N8195C; Carey, ID

Narrative:

Ms MacNichol had questions regarding the maintenance logbooks and airworthiness directive compliance. She indicated that she had a maintenance individual examine the wreckage with her, and they determined that the wing lift strut bolts had cut threads installed, not the rolled threads as required by Airworthiness Directive AD 99-01-05. She pointed out that the maintenance logbooks indicated that the AD had been complied with.