

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR15FA268	

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, WA
EVIDENCE OBTAINED BY: NTSB IIC - Thomas Little		
☒ EVIDENCE OBTAINED FROM: ☐ EVIDENCE RECEIVED FROM:	LOCATION OR PERSON INFORMATION Mr. Tom Downey Skagit Regional Airport Burlington, Washington	DATE 10/1/15 GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 001		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒) maintenance records for N8529G aircraft owner: Mr. Stephen L. Smith		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Tom	LAST NAME: Downey
ADDRESS: [REDACTED] Oak Harbor, WA. 98277-4564	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒	DATE: 10-5-2016 CONTACT: Tom Little, NTSB IIC, [REDACTED]

CHAIN OF CUSTODY

RELEASED BY: Tom Downey	RELEASED TO: Tom Little (NTSB IIC)	DATE: 10/1/15
PURPOSE: Accident investigation		
RELEASED BY: Tom Little	RELEASED TO: Rob Spencer Arnold & Arnold Insurance	DATE: 10.5.16
PURPOSE: Accident investigation (concluded)		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER:
	WPR15FA268

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, WA
EVIDENCE OBTAINED BY: NTSB IIC - Thomas Little		
☒ EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION	DATE
☐ EVIDENCE RECEIVED FROM:	Aurora Aviation Services	10/15/15
EVIDENCE CONTROL NUMBER WPR15FA268 2015-002	Jefferson County Airport, Port Townsend, WASHINGTON	GROUP AS/WPR
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒ left magneto (S/N: 98091282)		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Scott	LAST NAME: Erickson
ADDRESS: Aurora Aviation Services [REDACTED], Port Townsend, WA 98368	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☐	DATE:
CONTACT:	

CHAIN OF CUSTODY

RELEASED BY: Scott Erickson	RELEASED TO: Tom Little	DATE: 10/15/15
PURPOSE: Accident Investigation		
RELEASED BY: Tom Little	RELEASED TO: Clifford Carpenter (FAA)	DATE: 10/29/15
PURPOSE: Accident Investigation - Magneto Examination		
RELEASED BY: Clifford Carpenter	RELEASED TO: Scott Erickson	DATE: 12/3/15
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER:
	WPR15FA268

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, WA
EVIDENCE OBTAINED BY: Thomas M. Little, NTSB IIC		
☒ EVIDENCE OBTAINED FROM: ☐ EVIDENCE RECEIVED FROM:	LOCATION OR PERSON INFORMATION Aurora Aircraft Maintenance Jefferson County International Airport, Port Townsend, Washington	DATE 10/15/15 GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 003		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒) GARMIN area 500		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Stephen	LAST NAME: Smith
ADDRESS: [REDACTED] Lake Stevens, Washington 98258	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒ DATE: 12/23/16	CONTACT: Sarah McComb Chief RE-40 NTSB

CHAIN OF CUSTODY

RELEASED BY: Tom Little (NTSB IIC)	RELEASED TO: Sarah McComb NTSB Chief RE-40	DATE: 10/21/15
PURPOSE: Accident investigation		
RELEASED BY: SARAH McComb (RE-4)	RELEASED TO: DAVE SMITH	DATE: 12/23/16
PURPOSE: Accident investigation - RETURN of GARMIN GPS 500		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR15FA268
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, Washington
-------------------------------	---------------------------------	--

EVIDENCE OBTAINED BY: NTSB IIC - Thomas Little

☒ EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Aurora Aircraft Maintenance	DATE 9/29/16
☐ EVIDENCE RECEIVED FROM:	[REDACTED]	GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 004		

DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒)
 crankshaft gear (SN: N12HA044) crankshaft gear bolts - 4 (PN: 22532)
 crankshaft gear dowel pin - 1 (PN: 630651) starter (SN: 45530)
 crankshaft (PN: 653012)

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Scott	LAST NAME: Erickson
ADDRESS: [REDACTED] Jefferson County Airport, Port Townsend, Washington 98368	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☐	DATE: CONTACT:

CHAIN OF CUSTODY

RELEASED BY: Scott Erickson Aurora Aircraft Services	RELEASED TO: Tom Little NTSB IIC	DATE: 10/15/15
PURPOSE: accident investigation		
RELEASED BY: Tom Little	RELEASED TO: Mike Budinski, NTSB Chief, RE-30	DATE: 12/23/15
PURPOSE: accident investigation		
RELEASED BY: Joseph Panagiotou NTSB materials engineer	RELEASED TO: Tom Little NTSB IIC	DATE: 8/26/16
PURPOSE: accident investigation		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		