

**NATIONAL TRANSPORTATION SAFETY BOARD
RECEIPT OF PARTS**

ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
WPR15FA268

PART II - RELEASE OF PARTS

REGISTRATION NUMBER N8529G	MAKE Cessna	MODEL 150F
--------------------------------------	-----------------------	----------------------

DATE OF ACCIDENT/INCIDENT September 28, 2015	LOCATION Port Townsend, Washington
--	--

The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to:

OWNER OR OWNER'S REPRESENTATIVE - **Mr. Scott Erickson**


ADDRESS

Jefferson County International Airport


Port Townsend, Washington 98368

PARTS, PIECES, OR COMPONENTS RETAINED:

left magneto: s/n-98091282
starter: s/n-45530
crankshaft: s/n-N12HA04-4
upper and lower crankshaft gear bolts - 4
crankshaft gear cluster
crankshaft gear dowel pin

SIGNATURE OF NTSB REPRESENTATIVE 	TITLE Air Safety Investigator	DATE 10/27/2016
---	---	---------------------------

The registered owner or owner's representative will acknowledge receipt of the materials by signing this form in the spaces designated below.

SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE 	TITLE	DATE 11/1/2016
ADDRESS		