

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR15FA268
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, WA
EVIDENCE OBTAINED BY: NTSB IIC - Thomas Little		
☒ EVIDENCE OBTAINED FROM: ☐ EVIDENCE RECEIVED FROM:	LOCATION OR PERSON INFORMATION Mr. Tom Downey Skagit Regional Airport Burlington, Washington	DATE 10/1/15 GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 001		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒ maintenance records for N8529G aircraft owner: Mr. Stephen L. Smith		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Tom	LAST NAME: Downey
ADDRESS: [REDACTED], Oak Harbor, Washington 98277	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒	DATE: 10/5/16
CONTACT: Tom Little, NTSB IIC	

CHAIN OF CUSTODY

RELEASED BY: Tom Downey	RELEASED TO: Tom Little (NTSB IIC)	DATE: 10/1/15
PURPOSE: accident investigation		
RELEASED BY: Tom Little	RELEASED TO: Arnold & Arnold Insurance (Rob Spencer)	DATE: 10/5/16
PURPOSE: accident investigation		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR15FA268
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, Wash.
EVIDENCE OBTAINED BY: NTSB IIC - Thomas Little		
☒ EVIDENCE OBTAINED FROM: ☐ EVIDENCE RECEIVED FROM:	LOCATION OR PERSON INFORMATION Aurora Aircraft Maintenance 300 Airport Road, Port Townsend, Washington 98368	DATE 10/15/16 GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 002		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒) crankshaft gear (SN: N12HA044) crankshaft gear bolts - 4 (PN: 22532) crankshaft gear dowel pin - 1 (PN: 630651) crankshaft (PN: 653012)		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Scott	LAST NAME: Erickson
ADDRESS: [REDACTED], Jefferson County Airport, Port Townsend, Wash 98368	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒ DATE: 10/27/2016	CONTACT: Tom Little NTSB IIC

CHAIN OF CUSTODY

RELEASED BY: Scott Erickson Aurora Aircraft Services	RELEASED TO: Tom Little NTSB IIC	DATE: 10/15/15
PURPOSE: accident investigation		
RELEASED BY: Tom Little	RELEASED TO: Mike Budinski, NTSB Chief, RE-30	DATE: 12/23/15
PURPOSE: accident investigation		
RELEASED BY: Joseph Panagiotou NTSB materials engineer	RELEASED TO: Tom Little NTSB IIC	DATE: 8/26/16
PURPOSE: accident investigation		
RELEASED BY: Tom Little NTSB IIC	RELEASED TO: Scott Erickson Aurora Aircraft, owners representative	DATE: 10/27/16
PURPOSE: accident investigation		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR15FA268
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, WA
EVIDENCE OBTAINED BY: Thomas M. Little, NTSB IIC		
☒ EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION Aurora Aircraft Maintenance Jefferson County International Airport, Port Townsend, Washington	DATE 10/15/15
☐ EVIDENCE RECEIVED FROM:		GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 003		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒ GARMIN area 500		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Stephen	LAST NAME: Smith
ADDRESS: [REDACTED], Lake Stevens, Washington 98258	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒	DATE: 12/28/15
CONTACT: George Haralampopulos (NTSB RE-40)	

CHAIN OF CUSTODY

RELEASED BY: Scott Erickson Aurora Aircraft Services	RELEASED TO: Tom Little (NTSB IIC)	DATE: 10/15/16
PURPOSE: accident investigation		
RELEASED BY: Tom Little (NTSB IIC)	RELEASED TO: Sarah McComb NTSB Chief, RE-40	DATE: 10/21/15
PURPOSE: accident investigation		
RELEASED BY: George Haralampopulos	RELEASED TO: Stephen Smith	DATE: 12/28/15
PURPOSE: accident investigation - return of component to owner		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR15FA268
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, WA
EVIDENCE OBTAINED BY: NTSB IIC - Thomas Little		
☒ EVIDENCE OBTAINED FROM: ☐ EVIDENCE RECEIVED FROM:	LOCATION OR PERSON INFORMATION Aurora Aircraft Services, Jefferson County Airport, Port Townsend, Washington	DATE 10/15/15 GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 004		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒ left mangeto (S/N 98091282 Mfg: Slick Aircraft Products Model No.: 4301)		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Stephen	LAST NAME: Smith
ADDRESS: [REDACTED], Lake Stevens, Washington 98258	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒	DATE: 11/18/15
CONTACT: Cliff Carpenter, FAA inspector	

CHAIN OF CUSTODY

RELEASED BY: Scott Erickson, Aurora Aircraft Services	RELEASED TO: Tom Little (NTSB IIC)	DATE: 10/15/15
PURPOSE: Accident investigation - left magneto examination		
RELEASED BY: Tom Little (NTSB IIC)	RELEASED TO: Cliff Carpenter, Aviation Safety Inspector, Helena FSDO	DATE: 10/29/15
PURPOSE: accident investigation		
RELEASED BY: Cliff Carpenter, Aviation Safety Inspector, Helena FSDO	RELEASED TO: Aurora Aircraft Services, Scott Erickson	DATE: 11/18/15
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR15FA268
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 9/28/15	ACCIDENT LOCATION (City & State) Port Townsend, WA
EVIDENCE OBTAINED BY: Thomas M. Little, NTSB IIC		
☒ EVIDENCE OBTAINED FROM: ☐ EVIDENCE RECEIVED FROM:	LOCATION OR PERSON INFORMATION Aurora Aircraft Maintenance Jefferson County International Airport, Port Townsend, Washington	DATE 11/3/15 GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR15FA268 - 2015 - 005		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒ airplane's starter (SN: 45530)		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Scott	LAST NAME: Erickson
ADDRESS: [REDACTED], Jefferson County Airport, Port Townsend, Wash 98368	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒	DATE: 11/3/15
CONTACT: Scott Erickson	

CHAIN OF CUSTODY

RELEASED BY: Scott Erickson Aurora Aircraft Services	RELEASED TO: Tom Little, NTSB IIC	DATE: 11/3/15
PURPOSE: accident investigation - part sent to NTSB IIC, at the request of the NTSB IIC, Tom Little		
RELEASED BY: Tom Little, NTSB IIC	RELEASED TO: Scott Erickson Aurora Aircraft Services	DATE: 10/27/16
PURPOSE: accident investigation		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		