

LEFT
\$ 4.95



The Standard

PROPELLER LOG

ASA-SP-L

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2015	Total Time in Service	Description
Date: 3/2	271.3	HOBBSS: 2913.3
Next Inspection Due:	Time Since Overhaul	I CERTIFY THAT THIS PROP WAS INSPECTED IN ACCORDANCE WITH AN 100 HOUR INSPECTION. APPROVED FOR RETURNED SERVICE
	271.3	Mech. Cert. # or Repair Station # A8T [REDACTED] [REDACTED]
Year: 2016	Total Time in Service	Description
Date: 4/12	404.6	HOBBSS: 3046.6
Next Inspection Due:	Time Since Overhaul	REMOVED PROP FOR REPAIR
		Mech. Cert. # or Repair Station # A8P [REDACTED] [REDACTED]
Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair

28 APR 2016

TTSN 404.6 TTSO N/A

Repaired and functional tested.

Refer to work order # 12031

and 8130-3 # 36392.

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair

Brooke Warner

Warner Propeller Tucson, AZ

FAA CRS# W59R659N



Year: 2016	Total Time in Service	Description
Date: 5/2	404.6	
Next Inspection Due: _____	Time Since Overhaul	HOBBS: 3046.6 INSTALLED PROP. I CERTIFY THAT THIS PROP WAS INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND IS APPROVED FOR RETURN TO SERVICE
		Mech. Cert. # or Repair Station # AQP [REDACTED] [REDACTED]