

DOG BONE LLC

CASA GRANDE, AZ. 85222

N20844 MAKE: CESSNA MODEL: C-182P S/N: 18261251
23 Nov 2015 TACH: 0770.5 TTAF: 3458.0

All wheel bearings repacked by owner
ELT batteries removed, Inspected, New batteries installed, Expire 2020
Owner replaced induction air filter
All flight controls inspected and lubricated
AD 2011-10-09 Seat tracks & Rollers. AD complied with.
Re inspect at each 100 Hrs or next annual insp. Which ever comes first
Elt functional check in accordance with FAR 91.207d complied with & ok
Static wick on elevator to be replaced by owner
Proper documentation paperwork inspected for configuration to jump plane, inspected —
Oil drain safety wire removed and replaced
All AD's checked thru bi weekly 2015-23. No new ADs

I certify that this aircraft has been inspected in accordance with an Annual Inspection
In accordance with Far Part 43 Appendix D and Manufacturers Maintenance Manuals,
And found to be in ~~airworthy~~ condition at this time

~~STEPHEN HARTWELL A&P~~ ~~IA~~

Av Time

Airframe Serial Number 18267251			
Date	Tach Time	AFTT	FAA#
19 Sept 12	0612.5	3299.5	
Performed by:			

DOG BONE LLC

CASA GRANDE, AZ. 85222

N20844 MAKE: CESSNA MODEL: C-182P S/N: 18261251
19 Sept 2012 TACH: 0612.5 TTAF: 3299.5

Removed, repacked and reinstalled all wheel bearings
Remove and replaced vacuum filter
ELT batteries removed and replaced, Expire Sept 2018
Removed and replaced induction air filter
All flight controls inspected and lubricated
AD 2011-10-09 Seat tracks & Rollers. AD complied with.
Reinspect at each 100 Hrs or next annual insp. Which ever comes first
Elt functional check in accordance with FAR 91.207d complied with & ok
Repaired L/H navigation light and strobe light
Electrical wires under L/H floor secured
Tie wraps removed and wires secured in cable clamp under floor
L/H and R/H wing tip caps, stop drilled cracks
All AD's checked thru bi weekly 2012-18.

Date

Perf

I certify that this aircraft has been inspected in accordance with an Annual Inspection
In accordance with Far Part 43 Appendix D and Manufacturers Maintenance Manuals,
And found to be in airworthy condition at this time

STEPHEN HARTWELL A&P [REDACTED] IA

337's executed as well see 337. RTR Floor Carpet

Remove and installed Right rear interior panels w/2024T-3, 32G
Aluminum. (Far 42 Upstitch repair)

19 Sept 12 0612.5 returned to service