

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: WPR16IA100
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 4/29/16	ACCIDENT LOCATION (City & State) San Carlos, California
EVIDENCE OBTAINED BY: NTSB IIC - Thomas Little		
☒ EVIDENCE OBTAINED FROM: ☐ EVIDENCE RECEIVED FROM:	LOCATION OR PERSON INFORMATION Michael Arraiz San Jose Flight Standards District Office San Jose, California	DATE 6/16/16 GROUP AS/WPR
EVIDENCE CONTROL NUMBER WPR16IA100 - 2016 - 001		
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☒) airplane's throttle cable		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME: Daniel	LAST NAME: Dyer
ADDRESS: [REDACTED], San Carlos, California 94070	
PHONE: [REDACTED]	EMAIL: [REDACTED]
RETURNED ☒	DATE: 12/23/16 CONTACT: Matt Fox, NTSB RE-30, [REDACTED]

CHAIN OF CUSTODY

RELEASED BY: Tom Little (NTST IIC)	RELEASED TO: Mike Budinski (Chief, RE-30)	DATE: 6/16/16
PURPOSE: accident investigation		
RELEASED BY: Matt Fox (NTSB RE-30)	RELEASED TO: Dan Dyer	DATE: 12/23/16
PURPOSE: accident investigation (return of throttle cable to operator)		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		