

Smith Maja

To: Paul.Alukonis [REDACTED]
Subject: Throttle Arm N20XY

From: Paul.Alukonis [REDACTED] [mailto:Paul.Alukonis [REDACTED]]
Sent: Thursday, January 07, 2016 3:22 PM
To: Smith Maja <maja.smith [REDACTED]>
Cc: kgibson [REDACTED]; Gavin.McCune [REDACTED]
Subject: RE: Throttle Arm N20XY

The fuel was drained from the left tank. Even when level the fuel was not visible. However, approximately 12 gallons were recovered from that tank. The right tank was full.

Paul R. Alukonis
Principal Operations Inspector

Federal Aviation Administration
[Nevada Flight Standard District Office](#)
Phone: [REDACTED] | FAX: [REDACTED]
E-Mail: [Paul.Alukonis \[REDACTED\]](#)