

Airframe Entries

Performed 100 hr inspection IAW with Robinson R22 MM 2460. Complied with AD 2011-12-10. Blade skin debonding by inspection. Inspected
 sent to spare part noted at this time. Next due tach=1233.1. Replaced tail rotor gearbox input shaft seal and O-rings per RHC R22 MM 7.470.
 Replaced collective spring lower inner mounting support tab. I certify that this aircraft has been inspected in accordance with a 100 Hr inspection and
 was determined to be in a worthy condition at this time.

Maintenance Release

The aircraft and/or component(s) on N7020U was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and
 was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 0374. Dated: 11/24/2014.

DATE 11/24/2014

SIGNED

Steven Thompson, A&P

Work Order 0374

Printed by EBis 3 (datcomedia.com)

N7020U

11-24-14

A/C TSN 7558

HOBS 1332

REMOVE AND REPLACED B245-1 Gov Reg
 MOTOR ASSY I.A.W R.M.M. Sec. 8.233 AND 8.224
 PERFORMED SYS OPS CK A/C RUNS AND GOW CK
 PER PUSH + mm ck List sys ops ck NORMAL
 A/C Found to be in Service At this time -END-
 A+P#

INSPECTION RECORD

DATE 5/15/2015
 A/C TSN 7558.3
 ENG TT 1025
 TACH 1310.4

DATE

ENGINE MODEL
 ENGINE S/N
 REG NO N7020U
 WORK ORDER 0106

XL Air Service, LLC.

North Las Vegas, NV 89032
 Phone

DATE 7/17/2015
 A/C TSN 8015.7
 ENG TT 4953
 TSMOH 1369.8
 HOBS 1369.8

Engine Entries

Removed left and right magnetos. Installed Aircraft Electrical Components Inc overhauled magnetos. Timed magnetos to engine.
 Changed oil and filter. Cut open filter, inspected, no metal found. Service with 6 Qt's of Phillips X/C 20W50. Ground run, no leaks
 noted.

Maintenance Release

The aircraft and/or component(s) on N7020U was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and
 was found Airworthy for return to service. Pertinent details of the repair are on file at XL AIR SERVICE LLC, under Work Order No. 0106. Dated
 7/17/2015.

DATE 7/17/2015

SIGNED

Steve Thompson, A&P

Work Order 0106

Printed by EBis 3 (datcomedia.com)

Current FARs rules of the Federal Aviation Regulations and
 SERVICE LLC, under Work Order No. 0072. Dated

Work Order: 0072

Printed by EBis 3 (datcomedia.com)

DATE 6/3/2015
 A/C TSN 7558.1
 ENG TT 4895.4
 TSMOH 1332.2
 HOBS 1332.2