

METARs

Accident 2/16/16 1452 MST = 2052 UTC

Wx facility at accident location

KBXK	162335Z	AUTO	26003KT	10SM	CLR	29/M01	A2988	RMK	A01
KBXK	162315Z	AUTO	00000KT	10SM	CLR	28/00	A2989	RMK	A01
KBXK	162255Z	AUTO	00000KT	10SM	CLR	28/00	A2989	RMK	A01
KBXK	162235Z	AUTO	14003KT	10SM	CLR	28/00	A2990	RMK	A01
KBXK	162215Z	AUTO	12004KT	10SM	CLR	28/00	A2990	RMK	A01
KBXK	162155Z	AUTO	15004KT	10SM	CLR	28/M02	A2991	RMK	A01
KBXK	162135Z	AUTO	14006KT	10SM	CLR	27/M01	A2992	RMK	A01
KBXK	162115Z	AUTO	14007KT	10SM	CLR	27/M01	A2992	RMK	A01
KBXK	162055Z	AUTO	13008KT	10SM	CLR	27/02	A2993	RMK	A01
KBXK	162035Z	AUTO	13009KT	10SM	CLR	27/02	A2994	RMK	A01
KBXK	162015Z	AUTO	13009KT	10SM	CLR	26/03	A2995	RMK	A01
KBXK	161955Z	AUTO	13009KT	10SM	CLR	25/03	A2996	RMK	A01
KBXK	161935Z	AUTO	13009KT	10SM	CLR	25/02	A2997	RMK	A01
KBXK	161915Z	AUTO	12012KT	10SM	CLR	25/02	A2998	RMK	A01
KBXK	161855Z	AUTO	09012KT	10SM	CLR	25/00	A2999	RMK	A01
KBXK	161835Z	AUTO	09010KT	10SM	CLR	25/00	A3000	RMK	A01
KBXK	161815Z	AUTO	11012KT	10SM	CLR	24/00	A3001	RMK	A01
KBXK	161755Z	AUTO	13004KT	10SM	CLR	23/02	A3002	RMK	A01