

METARs

Accident 5/13/16 1530 PDT = 2230 UTC

Wx facility at accident location

KMHV 140000Z AUTO 21017KT 10SM CLR 30/00 A2996 RMK A01
KMHV 132340Z AUTO 22018KT 10SM CLR 31/00 A2996 RMK A01
KMHV 132320Z AUTO 22021G27KT 10SM CLR 31/01 A2996 RMK A01
KMHV 132300Z AUTO 22016G24KT 10SM CLR 32/01 A2996 RMK A01
KMHV 132240Z AUTO 22018KT 10SM CLR 32/01 A2996 RMK A01
KMHV 132220Z AUTO 21015KT 10SM CLR 32/M02 A2995 RMK A01
KMHV 132200Z AUTO 18012KT 10SM CLR 33/M04 A2996 RMK A01
KMHV 132140Z AUTO 11008G17KT 10SM CLR 33/M04 A2997 RMK A01
KMHV 132120Z AUTO VRB03KT 10SM CLR 32/M04 A2998 RMK A01
KMHV 132100Z AUTO 13012KT 10SM CLR 32/M04 A2999 RMK A01
KMHV 132040Z AUTO VRB04G12KT 10SM CLR 31/M04 A2999 RMK A01
KMHV 132020Z AUTO 20015KT 10SM CLR 32/M04 A3000 RMK A01
KMHV 132000Z AUTO 23006G12KT 10SM CLR 31/M02 A3001 RMK A01
KMHV 131940Z AUTO 13008KT 10SM CLR 30/M00 A3002 RMK A01
KMHV 131920Z AUTO VRB04G10KT 10SM CLR 30/01 A3002 RMK A01
KMHV 131900Z AUTO VRB04KT 10SM CLR 29/00 A3003 RMK A01
KMHV 131840Z AUTO VRB04KT CLR 29/01 A3004 RMK A01
KMHV 131820Z AUTO VRB05G10KT 10SM CLR 29/02 A3003 RMK A01
KMHV 131800Z AUTO 00000KT 10SM CLR 28/02 A3004 RMK A01
KMHV 131740Z AUTO 00000KT 10SM CLR 27/04 A3004 RMK A01
KMHV 131720Z AUTO 09006KT 10SM CLR 27/05 A3004 RMK A01
KMHV 131700Z AUTO 00000KT 10SM CLR 26/05 A3004 RMK A01
KMHV 131640Z AUTO 00000KT 10SM CLR 26/05 A3004 RMK A01