

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Prescott State: AZ

ZIP: 86301 Country: USA

Latitude: N34 39.2900' Longitude: W112.25.1533'

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 06/18/2016 Local Time: 08:15
mm/dd/yyyy

Time Zone: MT

Collision with Other Aircraft: ☐ Midair ☒ On-ground ☐ None

AIRCRAFT INFORMATION

Registration Number: N9246S

Manufacturer: Beechcraft

Model: C-23 Sundowner

Serial Number: M-1742

Year of Manufacture: 1975

Amateur-Built: ☐ Yes ☒ No
If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 2450 lbs

Weight at Time of Accident/Incident: _____ lbs

Number of Seats: 2 Flight Crew Seats: 2

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate (Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

- ☐ Retractable
☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel

☐ Other Launch/Recovery System

☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Lycoming	O&VO-360	L-20500-36A		180	3958	25	25
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 03/24/2016

mm/dd/yyyy

Airframe Total Time: 3958 hrs

hours measured at (Select one)

- ☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Handheld Fire Extinguisher

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Senserich

Model: _____

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft: ☒ Yes ☐ No

If not activated:

Indicate Reason:

- ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☒ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Joyce A. ParkerCity: TopekaState: KSZIP: 66619Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☒ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Ernest Love Field - PrescottAirport Identifier: KPRCProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/ADistance From Airport Center: 1/2 sm

Direction From Airport: _____ degrees true

Airport Elevation: 5044 ft. msl**Runway Information**Runway ID: 21L (L/R/C) Length: 7619 ft Width: 150 ft**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☒ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Crosswind ☐ Aborted Landing (after touchdown)
☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☒ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☐ Yes ☒ No

"Flight Crewmember 1" Identification

First Name: Joyce City of Residence: Topeka
 Middle Initial: A State: KS ZIP: 66619
 Last Name: Parker Country: USA
 Age at time of Accident/Incident: 58 Date of Birth: 1957 mm/dd/yyyy
 Certificate Number:

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table border="0"> <tr> <th>Available</th> <th>Used</th> </tr> <tr> <td> ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown </td> <td> ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown </td> </tr> </table>	Available	Used	☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used						
☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown						
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance					
Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	Date of Last Medical <u>05/05/2016</u> mm/dd/yyyy					

Medical Certificate Limitations

Must wear corrective lenses.

Medical Certificate Special Issuance

Date of Last Flight Review
 or Equivalent, Including
 FAR 121/135 Checks: 05/05/2016
 mm/dd/yyyy

Flight Review Aircraft

Make: Beechcraft
 Model: C-23 Sundowner

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☒ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
---	---	--	---

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	469	215	469		35	6	38			
Pilot in Command (PIC)	356	206	356							
Time as Instructor	0	0	0							
This Make/Model										
Last 90 Days	30	30	30		0	0	0			
Last 30 Days	20	20	20		0	0	0			
Last 24 Hours	11	11	11		0	0	0			

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☐ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None
 ☐ Instrument Airplane
☐ Airplane Single-Engine
 ☐ Instrument Helicopter
☐ Airplane Multi-Engine
☐ Helicopter
☐ Gyroplane
☐ Glider
☐ Powered Lift
 ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: Athina

City of Residence: Boynton Beach

Middle Initial: A

State: Florida ZIP: 33437

Last Name: Holmes

Country: USA

Age at time of Accident/Incident: 50 Date of Birth: 1965 mm/dd/yyyy

Certificate Number: _____

Degree of Injury

☐ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☒ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☒ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☒ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☒ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

11/10/2014
mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

10/25/2016
mm/dd/yyyy

Flight Review Aircraft

Make: Cessna

Model: 172 SP

Airplane Rating(s) (Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☒ None
☐ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☐ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	465	52	383	6	19	10	97			
Pilot in Command (PIC)	325		325							
Time as Instructor										
This Make/Model										
Last 90 Days	15									
Last 30 Days										
Last 24 Hours	11									

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)

Crew Name and Address

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

Seat Occupied

☐ Left ☐ Front
☐ Center ☐ Rear
☐ Right ☐ Single
☐ Unknown

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Restraint Type:

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Type Rating/Endorsement for Accident/Incident Aircraft?

☐ Yes ☐ No

Total Flight Time at the Time of this Accident/Incident: _____ hrs

Crew Name and Address

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____

Seat Occupied

☐ Left ☐ Front
☐ Center ☐ Rear
☐ Right ☐ Single
☐ Unknown

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Restraint Type:

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Type Rating/Endorsement for Accident/Incident Aircraft?

☐ Yes ☐ No

Total Flight Time at the Time of this Accident/Incident: _____ hrs

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)

Name and Address

First Name: _____ City : _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
☐ Crew ☐ Passenger ☐ Other

Seat

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

Injury

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Restraint Type

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Age

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City : _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City : _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

First Name: _____ City : _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
☐ Crew ☐ Passenger ☐ Other

☐ Left
☐ Center
☐ Right
☐ Unknown
 Row: _____

☐ None
☐ Minor
☐ Serious
☐ Fatal
☐ Unknown

Available **Used**
☐ None ☐ None
☐ Lap Only ☐ Lap Only
☐ 3-point ☐ 3-point
☐ 4-point ☐ 4-point
☐ 5-point ☐ 5-point
☐ Unknown ☐ Unknown

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

☐ Under 5 years
 If Under 5,
☐ Child Restraint
☐ Lap-Held
☐ Unknown

FLIGHT ITINERARY INFORMATION					
Last Departure Point Airport ID: <u>KGNT</u> City: <u>Grants</u> State: <u>NM</u> Country: <u>USA</u>		Time of Departure Time: <u>07:15</u> Time Zone: <u>MT</u>		Destination Airport ID: <u>KPRC</u> City: <u>Prescott</u> State: <u>AZ</u> Country: <u>USA</u>	
Type Flight Plan Filed ☐ None ☐ Company VFR ☐ Military VFR ☒ VFR ☐ VFR/IFR ☐ IFR ☐ Unknown ☐ Unknown Activated? ☒ Yes ☐ No ☐ Unknown					
Type of ATC Clearance/Service (Check all that apply) ☐ None ☒ VFR ☐ Special VFR ☐ IFR ☐ Special IFR ☐ VFR On Top ☒ VFR Flight Following ☐ Traffic Advisory ☐ Cruise ☐ Unknown / NA					
Airspace where the accident/incident occurred (Check all that apply) ☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E ☐ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area ☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93 ☐ Special ☐ Air Traffic Control Area ☐ Unknown Altitude of In-Flight Occurrence: <u>9500</u> ft msl					
WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE					
Source of Pilot Weather Information (Check all that apply) ☒ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather ☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown			Weather Observation Facility Facility ID: _____ Observation Time: _____ Time Zone: _____ Distance from Accident Site: _____ nm Direction from Accident Site: _____ degrees true		
Basic Conditions ☒ VMC ☐ IMC ☐ Unknown		Light Condition ☐ Dawn ☒ Day ☐ Dusk ☐ Night ☐ Dark Night ☐ Bright Night ☐ Unknown			
Sky/Lowest Cloud Condition ☒ Clear ☐ Few ☐ Partial Obscuration ☐ Scattered ☐ Thin Broken ☐ Thin Overcast ☐ Unknown		Ceiling ☒ None (Clear) ☐ Broken ☐ Overcast ☐ Obscured ☐ Indefinite ☐ Unknown		Temperature: <u>23</u> (C) or _____ (F) Dew Point: _____ (C) or _____ (F) Altimeter Setting: <u>30.27</u> in. Hg or _____ MB	
Lowest Cloud Condition Height _____ ft agl		Ceiling Height _____ ft agl			
Wind Direction ☐ Variable -or- Direction: <u>225</u> degrees true	Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: <u>04</u> kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts	Visibility <u>10</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: _____ ft		
Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☒ N/A ☐ Unknown		Type of Precipitation (Check all that apply) ☒ None ☐ Rain ☐ Snow ☐ Hail ☐ Rain Showers ☐ Drizzle ☐ Ice Pellets ☐ Snow Pellets ☐ Snow Grains ☐ Ice Crystals ☐ Freezing Rain ☐ Snow Shower ☐ Ice Pellets Shower ☐ Freezing Drizzle		Restriction to Visibility (Check all that apply) ☒ None ☐ Blowing Dust ☐ Blowing Sand ☐ Blowing Snow ☐ Blowing Spray ☐ Dust ☐ Fog ☐ Ground Fog ☐ Haze ☐ Ice Fog ☐ Smoke ☐ Unknown	
Icing Forecast Amount ☐ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☐ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown		Icing Actual Amount ☐ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☐ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown		Turbulence Type (Check all that apply) ☐ None ☐ Clear Air ☐ Terrain-Induced ☐ Convective Turbulence Severity ☐ Light ☐ Moderate ☐ Severe ☐ Extreme	
NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident: 					

DAMAGE TO AIRCRAFT AND OTHER PROPERTY

Aircraft Damage

- ☐ None
☐ Minor
☒ Substantial
☐ Destroyed
☐ Unknown

Aircraft Fire

- ☐ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Fire at Unknown Time
☐ Unknown

Aircraft Explosion

- ☒ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Explosion at Unknown Time
☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Tricycle fixed gear totally sheared off acct; one propeller blade of 2-blade propeller bent/curled; left wing rippled/damaged; wing tip nav lights & strobes broken off; tail rotating beacon and strobe broken; right passenger door; right fuselage damaged; right door won't close; pitot tube broken off; engine exhaust pipe damaged

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

On Friday, June 17, 2016, Athina Holmes, copilot and Joyce Parker, pilot and owner of Beechcraft C-23 Sundowner N9246S departed Billard Airport, (KTOP) Topeka, KS at 08:15 CT enroute to Ernest Love Field, (KPRC) Prescott, AZ to participate in the 2016 Women's Air Race Classic. We departed to the west in clear weather conditions, full tanks (52 gal usable fuel) and established a cruise altitude of 6,500 ft at which time I leaned the mixture for best power. We flew for 4 hours and stopped at Dalhart Municipal Airport (KDHT), Dalhart, TX for fuel. We purchased 35.5 gallons of fuel (filled tanks) and departed again to the west towards Tucumcari, NM. After reaching cruise altitude of 8500', I proceeded to lean the mixture. Moments after leaning the mixture and being established at best power, we suddenly lost engine power. I immediately pushed the mixture back in and turned on the fuel boost pump. After descending approximately 1000' feet, the engine "came back to life", we climbed back to altitude, and I took care in leaning the mixture. We proceeded towards Albuquerque, when we were informed by Albuquerque Center of the firefighting TFR along our route of flight. After 2:20 minutes of flight, we landed in Sandia, NM (1N1) to determine our route of flight to get around the TFR. We conferred with Flight Service and after 45 minutes on the ground, we departed Sandia (1N1) heading east and flew a route from 1N1 to OTO VOR to CNX VOR to ONM VOR to Socorro Airport (KONM). This flight was 1:25 minutes. We landed at Socorro and and put 27 gallons of fuel in the tanks. The left tank was full at 26 gals usable and the right tank was at the horizontal slot on the filler tab indicating 15 gals usable. Knowing that the left tank was the fullest tank, we departed with the fuel selector on the left tank. We determined that we could make Prescott in 3hrs, so we departed and proceeded on course northwest to Grants-Milan (KGNT). After reaching cruise altitude of 8500', I proceeded to lean the mixture for best power. Moments later after setting the mixture for best power, the engine lost power again and we were frantically trying to figure out what was happening and why. I put the fuel boost pump on, pushed the mixture back in, pushed the power back in, then I believe I pulled the mixture back out a little. After about 20 or so seconds, the engine again "came back to life". At this point, we decided we would not try to make it to Prescott, we were confused as to what and why this was happening, and because the sun was beginning to set, we decided to land at Grants-Milan, NM and spend the evening. I informed Athina that I would call my mechanic in the morning to find out what could possibly be the problem with two engines anomalies that day.

The next morning, we arrived at the airport at approx 5:45, I checked weather along our route of flight, filed our VFR flight plan while Athina, my copilot did the preflight on the airplane. The temperature had dropped down to 42 degrees F the previous evening, so the air was a bit chilly but crisp. Upon preflight, we discovered the stall warning horn did not work. At 6:30, I called my mechanic, Keith Hetrick, of Hetrick Aviation, Topeka, KS (KTOP) and explained to him the two engine problems we had the day before, along with the stall warning horn problem, and questions about my new ammeter/voltage regulator. For the engine problem, Keith suggested it might be vapor lock due to the density altitude and temperature conditions we were flying in. He directed me on engine runup to run the engine at 2400 rpm instead of 2200 rpm and then lean the mixture for best power there on the ground and then leave it there. We completed our predeparture checklist, ensured fuel selector was on left tank since it was the fullest tank from the fueling the previous evening in Socorro and we only flew 1 hour from Socorro to Grants-Milan. We departed Grants-Milan at 7:15 MT with 2 hours enroute to Prescott. We departed uneventfully to the northwest and established a cruise altitude of 10,500'. I did not lean the mixture at all during this flight. At approximately 1:10 minutes into the flight, I looked at my tablet and determined that we had 49 minutes left to Prescott, so I switched the fuel selector to the right tank believing at this point that there was now more fuel in the right tank than the left. We proceeded on at 10,500' and when we crested Mingus Mountain, we were looking for the airfield. When we had KPRC in sight, I contacted Albuquerque Center, informing them we had the airfield in sight, cancelling flight following, requesting frequency change. I then began to run the descent checklist. I obtained the ATIS weather, then contacted tower informing them we were inbound. I also informed my copilot Athina, who was flying the aircraft, (I was piloting when we departed, established our 10,500' cruise altitude, then turned the plane over to Athina) that we needed to lose 5,500' ft of altitude. I then went through the checklist: fuel boost pump on, carb heat on then off, gas fullest tank (right tank), gear down, mixture full rich, prop is spinning, seat belts & safety switches = landing light on. At that point, we pulled the power back to 1800 or 1900 rpm and then the engine quit again. We immediately pushed the power back in but nothing happened, I pull the mixture out, then pushed it back in; still no response from the engine. Then momentarily it felt as if we had a burst of power back, so I gradually pulled the mixture back out...then no more power. I proceeded trying a restart with the starter to no avail. I called tower and informed them we were having an engine emergency and they cleared us to land on Runway 21L. They asked how far we were from the field; I responded 3.2 miles. We were descending at approximately 700-800 fpm then all of a sudden the stall warning horn sounded. I told Athina to get the nose down. She determined that we were not going to make the runway because of the the 30 degree turn we were going to have to execute, so she decided to land it straight ahead. We continued to descend, flying past brush then we hit the ground and

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

More training in density altitude, high temperature, mountain flying, & leaning procedures training
If the cause of the three engine anomalies was vapor lock, I should have switched fuel tanks; I did turn on the fuel boost pump, but knowing that I had fuel in those tanks, I didn't register it as being a fuel issue.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Engine failed to restart after initiating restart procedures

Total Time/Cycles
On Part3958 Hours

Cycles

Time Since This Part
Inspected/Overhauled25 Hours**FUEL & SERVICES INFORMATION**

Fuel on Board at Last Takeoff

(Convert from pounds, as necessary)

36 Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Both pilots exited immediately through the left and right doors

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

going approximately 80 mph at which point we hit a mound (perhaps) that catapulted us back up into the air where moments later we came crashing down and stopped. We were both conscious and cognizant of what was going on and were ok. Her door had flung open (not sure how/when) and I immediately turned the fuel selector to off and took the keys out of the start, laid them on the dash, then exited the airplane on the left. Athina had bumped her knees and got a cut on her right leg; I suffered no injuries.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

06/29/2016

mm/dd/yyyy

Name of Pilot/Operator: Joyce A Parker

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR16LA128

Reviewed by NTSB Regional Office

WPR - Seattle

Name of Investigator

S. Stein

Date Report Received

June 29, 2016

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

06/29/2016

mm/dd/yyyy

Name of Pilot/Operator: Athina A. Holmes

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR16LA128

Reviewed by NTSB Regional Office

WPR - Seattle

Name of Investigator

S. Stein

Date Report Received

June 29, 2016