

[REDACTED]

[REDACTED]

[REDACTED]

Warranty

Engines overhauled by [REDACTED] will be warranted for a period of (12) months or (500) hours of operation, which ever occurs first, from date of first operation or (3) months from engine sign off date which ever occurs first, for defective parts and workmanship supplied by [REDACTED]. Normal maintenance not covered. Tim's Aircraft Engines Inc. will at its option repair or replace on an exchange basis any component or part sold by it within the (12) months or (500) hour warranty period found to be defective in material or workmanship.

All warranty claims must be approved by [REDACTED] Prior to commencing repairs. All warranty parts and labor to be supplied by [REDACTED] unless approved by [REDACTED]. Loss of use or down time of aircraft is not covered and will not be considered or compensated. Freight and transportation are not covered. Warranty void if engine is not maintained and operated per factory recommendations. New cylinders and Accessories are subject to Manufacturer's or vender's warranty which may be greater than (12) months.-----END-----

01/05/2017 13:03

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
--------------------	---------------------------	-------------------	-----------------------------	---

MAKE: LYCOMING
MODEL: O-360-J2A
SERIAL # L-39847-36A

N# : N702J
T.T. 4400.0
T.S.O.H. --0--

THE ENGINE LISTED ABOVE WAS OVERHAULED. THIS ENGINE WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, ASSEMBLED AND TESTED PER LYCOMING OVERHAUL MANUAL 60294-7-14 AND PARTS MANUAL PC306-11 FOR A MAJOR OVERHAUL. PERTINENT DETAILS ARE ON FILE AT THIS FACILITY UNDER INV. 8701. PARTS LIST ON NEXT PAGE. AD LIST IN BACK OF LOG. TEST RAN ENGINE IN ENGINE TEST CELL. END.

DATE: APRIL 30, 2014

SIGNED: [REDACTED]
FAA REPAIR STATION [REDACTED]

[REDACTED]
[REDACTED]
LONG BEACH, CA. 90805
PH. # [REDACTED]
FAX [REDACTED]

10-5217
BL-600644-201
BL-600614-1
ALY-8520

75BT4015
S/N 7512111
S/N E13LA138R
S/N E14BA216R
S/N H-0020101
H-P100448

CARBURETOR
MAGNETO
MAGNETO
ALTERNATOR

01/05/2017 13:04

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
--------------	---------------------------	-------------------	-----------------------------	--

N702JJ R22 S/N 3791
0-360-J2
Engine TT: 4403.0

Engine Log
S/N L-39847-36A
Engine TSO: 3.0 hrs

Dec. 19, 2015
Actt: 4403.0
Hobbs: 4403.0

Removed engine assembly Model 0-360-J2A S/N L-39847-36A ETT: 4400 hrs. and sent to Tim's Aircraft Engines Inc. for overhaul under Inv. #8701. Assembled and installed engine cooling panel field kit P/N R8299; installed overhauled engine oil cooler P/N 106147 S/N 1924; installed new (8) engine mounts P/N 71032. Installed overhauled engine; Installed new CH48108-1 oil filter and new air filter P/N A771-1. Installed B & C starter P/N BC315-100-2 S/N 0904000904; Installed alternator P/N ALY-8420-9 S/N H-P100448 TSN: 0.0 hrs. Installed repaired MA-4SPA carburetor P/N 10-5217 S/N 75BT4015. Serviced with 6 quarts of Aeroshell 100 mineral engine oil. Pre-oiled engine, cranked and assured engine oil was pumping thru out engine. Ground turned and leak checked. Adjusted engine idle RPM to 57% and engine oil pressure was in set to upper green arc in flight. Performed cylinder compression test as follows #1 79/80; # 2 79/80; # 3 79/80; # 4 79/80; - Complied with SB-366 carburetor body screws inspection AD's complied thru 2015-24.

"I certify that this engine has been inspected in reference with an Annual inspection and was found to be in an airworthy condition and is returned approved for return to service."

For

-----END-----

01/05/2017 13:04

RECORDING
TACH

TODAY'S
FLIGHT

TOTAL
TIME IN

Description of Inspections, Tests, Repairs and Alterations
Entries must be endorsed with Name, Rating and Certificate Number of
Inspected Facility. (See back pages for other specific entries.)

N702JJ R22 II S/N 3791
Eng. TT: 4959.7

S/N L-39847-36A

Engine Log Book

Eng. TS0: 559.7

Nov 14, 2016
Holds 4959.7

Performed cylinder 300hr SB-388B #1 .022"; #2 reamed was stuck .025"; #3 .018"; #4 .030";
removed, cleaned, gapped and rotated spark plugs; Ground turned and leaked checked
this engine is approved for returned to service. I certify that

For

END

01/05/2017 13:05

YEAR on	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of
------------	-------------------	-------------------	------------------	--

N702JJ R22 II S/N 3791
Eng. TT: 4989.3

S/N L-39847-36A

Engine Log Book

Eng. TS0: 589.4

Dec. 18, 2016
Hobbs: 4989.3

"I certify that this engine has been inspected in reference with a 100hr./Annual Inspection and was found to be in an airworthy condition and is returned to service"
Performed cylinder compression; #1 79/80; #2 79/80; #3 79/80; #4 79/80; removed, cleaned, capped and rotated spark plugs; Checked magneto to engine timing. Complied with SB-480E engine oil change, cleaned sump screen; replaced oil filter with new P/N CH48108-1; serviced with 6 qts. Aeroshell 100 oil Plus and replaced air filter with new P/N A771-1; Complied with SB-366 carburetor body for fuel stains, no defects found; Adjusted alternator belt tension; Ground turned and leaked checked. I certify that this engine is approved for returned to service. All AD's have been complied with thru 2016-22.

[Redacted Signature] I.A. [Redacted]
For [Redacted]

-----END-----

01/05/2017 13:05

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	---

11-18-16

N702JJ

Hobbs: 4959.8

Torrance, CA. 90505

MAGNETO p/n) 10-600644-201 s/n) E13LA138R

Performed 500hr inspection and repair. Disassembled, cleaned, inspected, replaced points, oil seal, and bench tested. Work performed as per the TCM manual and FAR43.13. Installed magneto and timed to engine data plate specs.

AP

11-18-16

N702JJ

Hobbs: 4959.8

Torrance, CA. 90505

MAGNETO p/n) 10-600614-1 s/n) E14BA216R

Performed 500hr inspection and repair. Disassembled, cleaned, inspected, replaced points, oil seal, d.e. bearing, and bench tested. Work performed as per the TCM manual and FAR43.13. Installed magneto and timed to engine data plate specs.

AP

01/05/2017 13:06