



RECORD OF EMAIL

Albert P. Nixon
Senior Aviation Accident Investigator
Western Pacific Region

Date: October 30, 2018
Person Contacted: Charles Wentworth (A & P Mechanic for WW1 Airplanes)
NTSB Accident Number: WPR17FA089

Narrative:

On an email with Charles Wentworth, mechanic of the accident airplane, the following is a summary of what he stated:

- The turnbuckles were under the seat.