

Name	ModeC	Name2	Mode3	Latitude	Longitude	F7
8:49:43 PM	2900	2900C	1200	37:34:43.68N	121:05:56.03W	SAC
8:49:55 PM	2900	2900C	1200	37:34:54.84N	121:05:23.62W	SAC
8:50:07 PM	2900	2900C	1200	37:35:07.08N	121:04:44.40W	SAC
8:50:19 PM	2900	2900C	1200	37:35:26.88N	121:04:07.32W	SAC
8:50:43 PM	2800	2800C	1200	37:35:59.99N	121:02:52.07W	SAC
8:51:19 PM	0	0C	1200	37:37:22.80N	121:00:50.04W	SAC
8:51:31 PM	2600	2600C	1200	37:37:37.56N	121:00:40.67W	SAC
8:51:55 PM	2500	2500C	1200	37:38:30.47N	120:59:21.49W	SAC
8:52:07 PM	2600	2600C	1200	37:38:49.92N	120:59:00.94W	SAC
8:52:19 PM	2600	2600C	1200	37:39:21.96N	120:58:17.77W	SAC
8:52:31 PM	2600	2600C	1200	37:39:45.72N	120:57:38.88W	SAC
8:52:55 PM	2600	2600C	1200	37:40:31.08N	120:56:35.51W	SAC
8:53:07 PM	2500	2500C	1200	37:40:54.12N	120:56:04.20W	SAC
8:53:19 PM	2600	2600C	1200	37:41:18.59N	120:55:27.48W	SAC
8:53:31 PM	2600	2600C	1200	37:41:41.99N	120:54:57.24W	SAC
8:53:43 PM	2600	2600C	1200	37:42:00.00N	120:54:18.70W	SAC
8:53:55 PM	2600	2600C	1200	37:42:23.76N	120:53:49.21W	SAC
8:54:07 PM	2500	2500C	1200	37:42:51.11N	120:53:08.50W	SAC
8:54:19 PM	2600	2600C	1200	37:43:17.04N	120:52:34.31W	SAC
8:54:31 PM	2500	2500C	1200	37:43:41.51N	120:52:06.24W	SAC
8:54:43 PM	2600	2600C	1200	37:44:09.60N	120:51:27.35W	SAC
8:54:55 PM	2600	2600C	1200	37:44:32.64N	120:51:06.11W	SAC
8:55:07 PM	2600	2600C	1200	37:44:54.24N	120:50:24.72W	SAC
8:55:19 PM	2600	2600C	1200	37:45:21.24N	120:49:53.03W	SAC
8:55:31 PM	2600	2600C	1200	37:45:47.15N	120:49:01.56W	SAC
8:55:43 PM	2600	2600C	1200	37:46:01.92N	120:48:43.18W	SAC
8:55:55 PM	2600	2600C	1200	37:46:26.76N	120:47:58.19W	SAC
8:56:07 PM	2600	2600C	1200	37:46:57.00N	120:47:23.28W	SAC
8:56:19 PM	2600	2600C	1200	37:47:18.23N	120:46:49.80W	SAC
8:56:31 PM	2600	2600C	1200	37:47:39.83N	120:46:17.04W	SAC
8:56:43 PM	2600	2600C	1200	37:48:01.79N	120:45:44.27W	SAC
8:56:55 PM	2600	2600C	1200	37:48:26.28N	120:45:07.19W	SAC
8:57:07 PM	2600	2600C	1200	37:48:53.28N	120:44:25.09W	SAC
8:57:19 PM	2600	2600C	1200	37:49:15.95N	120:43:53.75W	SAC
8:57:31 PM	2600	2600C	1200	37:49:34.68N	120:43:13.07W	SAC
8:57:43 PM	2600	2600C	1200	37:50:00.59N	120:42:37.45W	SAC
8:57:55 PM	2600	2600C	1200	37:50:24.00N	120:42:07.56W	SAC
8:58:07 PM	2600	2600C	1200	37:50:48.84N	120:41:17.88W	SAC
8:58:19 PM	2600	2600C	1200	37:51:10.44N	120:40:53.76W	SAC
8:58:31 PM	2600	2600C	1200	37:51:39.60N	120:40:15.23W	SAC
8:58:43 PM	2600	2600C	1200	37:52:06.95N	120:39:42.11W	SAC
8:58:55 PM	2600	2600C	1200	37:52:30.71N	120:38:58.90W	SAC
8:59:07 PM	2600	2600C	1200	37:52:52.31N	120:38:21.47W	SAC
8:59:19 PM	2600	2600C	1200	37:53:11.76N	120:37:48.73W	SAC
8:59:31 PM	2600	2600C	1200	37:53:36.96N	120:37:06.95W	SAC
8:59:43 PM	2600	2600C	1200	37:53:53.88N	120:36:39.24W	SAC

8:59:55 PM	2600 2600C	1200 37:54:16.92N	120:36:02.87W	SAC
9:07:44 PM	3100 3100C	1200 38:06:49.68N	120:35:13.54W	SAC
9:07:56 PM	3100 3100C	1200 38:07:15.96N	120:35:23.27W	SAC
9:08:08 PM	3100 3100C	1200 38:07:52.31N	120:35:34.80W	SAC
9:08:20 PM	3100 3100C	1200 38:08:29.76N	120:35:33.70W	SAC
9:08:32 PM	3100 3100C	1200 38:09:08.64N	120:35:43.78W	SAC
9:08:44 PM	3100 3100C	1200 38:09:42.48N	120:35:47.38W	SAC
9:09:08 PM	3300 3300C	1200 38:10:35.39N	120:36:09.00W	SAC
9:08:56 PM	3400 3400C	1200 38:10:04.79N	120:36:02.16W	SAC
9:09:20 PM	3100 3100C	1200 38:11:17.52N	120:36:06.11W	SAC
9:09:32 PM	3200 3200C	1200 38:11:47.76N	120:35:51.01W	SAC
9:09:44 PM	3500 3500C	1200 38:12:18.36N	120:35:36.59W	SAC
9:09:56 PM	3600 3600C	1200 38:12:35.99N	120:35:21.84W	SAC
9:05:32 PM	3800 3800C	1200 38:01:31.80N	120:30:20.15W	SAC
9:06:56 PM	3400 3400C	1200 38:04:42.23N	120:33:58.32W	SAC
9:07:20 PM	3100 3100C	1200 38:05:35.52N	120:34:53.38W	SAC
9:07:08 PM	3200 3200C	1200 38:05:07.79N	120:34:20.65W	SAC
9:06:32 PM	3400 3400C	1200 38:03:42.47N	120:33:11.16W	SAC
9:06:44 PM	3400 3400C	1200 38:04:13.44N	120:33:39.94W	SAC
9:07:32 PM	3100 3100C	1200 38:06:15.84N	120:34:59.87W	SAC
9:04:43 PM	3700 3700C	1200 38:00:38.16N	120:28:10.54W	SAC
9:05:20 PM	4000 4000C	1200 38:01:18.84N	120:29:44.50W	SAC
9:05:07 PM	3900 3900C	1200 38:01:05.87N	120:29:08.52W	SAC
9:04:55 PM	3800 3800C	1200 38:00:49.31N	120:28:36.11W	SAC
9:10:08 PM	3700 3700C	1200 38:13:15.60N	120:35:01.32W	SAC
9:10:20 PM	3800 3800C	1200 38:13:33.23N	120:34:47.64W	SAC
9:10:32 PM	4200 4200C	1200 38:13:57.36N	120:34:29.27W	SAC
9:10:44 PM	4200 4200C	1200 38:14:05.64N	120:34:11.99W	SAC
9:10:56 PM	4100 4100C	1200 38:14:19.68N	120:33:39.94W	SAC
9:11:08 PM	4100 4100C	1200 38:14:33.71N	120:33:07.92W	SAC
9:11:20 PM	4100 4100C	1200 38:14:54.60N	120:32:31.55W	SAC
9:11:32 PM	4100 4100C	1200 38:15:13.32N	120:32:08.15W	SAC
9:11:44 PM	4100 4100C	1200 38:15:35.27N	120:31:32.53W	SAC
9:11:56 PM	4200 4200C	1200 38:15:51.11N	120:31:01.19W	SAC
9:12:08 PM	4500 4500C	1200 38:16:07.67N	120:30:29.88W	SAC
9:12:20 PM	4300 4300C	1200 38:16:14.51N	120:29:53.87W	SAC
9:12:32 PM	4400 4400C	1200 38:16:25.32N	120:29:16.08W	SAC
9:12:44 PM	4300 4300C	1200 38:16:42.95N	120:28:45.12W	SAC
9:12:56 PM	4400 4400C	1200 38:16:58.07N	120:28:05.16W	SAC
9:13:08 PM	4200 4200C	1200 38:17:06.35N	120:27:29.51W	SAC
9:13:20 PM	3900 3900C	1200 38:17:15.36N	120:26:53.50W	SAC