



Maintenance Transaction Record

MTR ID # 2759512

Page 1 of 7

CAMP Systems International



This Maintenance Report is To Be Used Solely For (Check One)

☒ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☐ APU
Serial No. _____

Aircraft Identification and Status

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSNTSO/TSR	Material Costs	Man Hours
050010	1 2	PERFORM WHEELS UP 10 DAY CHECK								
		Comments: Complied with GAMA Aviation 10 Day Check per Form Citation CE-560 Excel 10 day check form Rev 5/3/16.								
5-92-01	2 2	INSPECTION DOCUMENT 1								
		Comments: Complied with per the Cessna Model 560XL Maintenance Manual Chap 5-92-01. Operational checks good.								
B243001	3 2	FUNCTIONAL CHECK MAIN SHIP (UY006) BATTERY (CAPACITY CHECK) LEAD ACID : INSPECTION DOCUMENT 47		S3597-4		40757133				
		Comments: Complied with per the Cessna Model 560XL Maintenance Manual Chap 5-92-47 and Battery Manufacturer's Instructions for Continued Airworthiness. Operational check good.								
B237006	4 2	FUNCTIONAL CHECK CVR UNDERWATER LOCATOR BEACON COCKPIT VOICE RECORDER UNDERWATER LOCATING DEVICE (ULD): INSPECTION DOCUMENT 36		DK120		SC22946				
		Comments: Complied with per the Cessna Model 560XL Maintenance Manual Chap 5-92-36. CVR ULD Battery Due: Oct 2019..								
250020	5 2	GAMA MONTHLY SAFETY INSPECTION								
		Comments: Completed GAMA Monthly Safety Inspection per GAMA Aviation LLC Monthly Safety Inspection Form Rev 50 dated 2/22/2016.								

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE.

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO	Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☒ Federal Aviation Administration ☐ Other (Specify) _____ and THIS STATEMENT IS TO CERTIFY THAT THE STATED MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURERS INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PRESERVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED. Work Inspected By DANIEL COLLINS _____ Certificate No. _____ Date 20-Aug-2017 Pertinent details of this maintenance are on file at _____ above Work/Service Order Number as applicable.					

Maintenance Log	
Section	Page
3	1

**CESCOM****Maintenance Transaction Record**

MTR ID # 2759512

Page 2 of 7

This Maintenance Report is To Be Used Solely For (Check One)

☒ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☐ APU
Serial No. _____

CAMP Systems International

Aircraft Identification and Status

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		NS03UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
340001	6 2	UPDATE NAV DATABASE								
		Expiration Date: 14-Sep-2017 Comments: Complied with universal FMS Nav Database update to cycle 1709 Worldwide 2000FT effective date 17-AUG-2017 to 14-SEPT-2017, all work was done IAW Universal Operators Manual 2423SV801/901.								
A80110	7 2	DETAILED INSPECTION APU STARTER/GENERATOR : INSPECTION DOCUMENT 26	APU	300SGL138Q-6		4887XL				
		Comments: Complied with per the Cessna Model 560XL Maintenance Manual Chap 5-92-26. Brush wear shows 90 percent brush life remaining.								
321020	8 1	LEFT MAIN LANDING GEAR BREATHER VENT	LEFT MAIN LANDING GEAR	QSB-5-SS		NSN	A	N 0 MTH 0 HRS		
		Comments: Removed part no: QSB-5-SS Removed serial no: NSN. Installed new breather vent per the Cessna Model 560XL Maintenance Manual Chap 32-10-20.								
321020	9 1	RIGHT MAIN LANDING GEAR BREATHER VENT	RIGHT MAIN LANDING GEAR	QSB-5-SS		NSN	A	N 0 MTH 0 HRS		
		Comments: Removed part no: QSB-5-SS Removed serial no: NSN. Installed new breather vent per the Cessna Model 560XL Maintenance Manual Chap 32-10-20.								
321003	10 1	LEFT MAIN LANDING GEAR TRUNNION	LEFT MAIN LANDING GEAR	6641630-41		26671180	A	N 0 LDG		
		Comments: Removed part no: 6641630-5 Removed serial no: 7. Installed new trunnion and complied with all required checks per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.								

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE,

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO	Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☒ Federal Aviation Administration ☐ Other (Specify) _____ and					
THIS STATEMENT IS TO CERTIFY THAT THE STATED MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURER'S INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.					
Work Inspected By	DANIEL COLLINS	Certificate No.	_____	Date	20-Aug-2017
Pertinent details of this maintenance are on _____ under the above Work/Service Order Number as applicable.					

Maintenance Log

Section	Page
3	2



Maintenance Transaction Record

MTR ID # 2759512

Page 3 of 7

This Maintenance Report is To Be Used Solely For (Check One)

CAMP Systems International

☒ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☐ APU
Serial No. _____

Aircraft Identification and Status

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
321003	11 1	RIGHT MAIN LANDING GEAR TRUNNION	RIGHT MAIN LANDING GEAR	6641630-42		26648881	A	N 0 LDG		
		Comments: Removed part no: 6641630-6 Removed serial no: 6. Installed new trunnion and complied with all required checks per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.								
321004	12 1	LEFT MAIN LANDING GEAR TRAILING LINK	LEFT MAIN LANDING GEAR	6641530-3		26929557	G	N 0 LDG		
		Comments: Removed part no: 6641648-15 Removed serial no: SN-UNKNOWN. Installed new trailing link and complied with all required checks per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01. Trailing link was replaced for compatibility with new trunnion assembly.								
321004	13 1	RIGHT MAIN LANDING GEAR TRAILING LINK	RIGHT MAIN LANDING GEAR	6641530-2		24993140F	G	N 0 LDG		
		Comments: Removed part no: 6641648-14 Removed serial no: SN-UNKNOWN. Installed new trailing link and complied with all required checks per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01. Trailing link was replaced for compatibility with new trunnion assembly.								
321011	14 1	LEFT MAIN LANDING GEAR TRAILING LINK SPACER	LEFT MAIN LANDING GEAR	6641533-2		26273752M	G	N 0 LDG		
		Comments: Removed part no: 6641533-1 Removed serial no: SN-UNKNOWN. Installed new trailing link spacer and complied with all required checks per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01. Trailing link spacer was replaced for compatibility with new trunnion assembly.								

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE.

Installed Part Status: N - New, R - Repaired/Rebuild, S - Serviceable, D - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO	Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☒ Federal Aviation Administration ☐ Other (Specify) _____ and THIS STATEMENT IS TO CERTIFY THAT THE STATED MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURERS INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PREPARED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED. Work Inspected By DANIEL COLLINS Certificate No. _____ Date 20-Aug-2017 Pertinent details of this maintenance are on file under the above Work/Service Order Number as applicable.					

Maintenance Log	
Section	Page
3	3

**CESCOM****Maintenance Transaction Record**

MTR ID # 2759512

Page 4 of 7

CAMP Systems International

This Maintenance Report is To Be Used Solely For (Check One)

☒ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☐ APU
Serial No. _____**Aircraft Identification and Status**

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
321011	15 1	RIGHT MAIN LANDING GEAR TRAILING LINK SPACER	RIGHT MAIN LANDING GEAR	6641533-2		26289029A	G	N 0 LDG		
Comments: Removed part no: 6641533-1 Removed serial no: SN-UNKNOWN. Installed new trailing link spacer and complied with all required checks per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01. Trailing link spacer was replaced for compatibility with new trunnion assembly.										
321031	16 1	LEFT MAIN LANDING GEAR FORWARD TRUNNION ATTACH PIN	LEFT MAIN LANDING GEAR	6641424-1		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN Removed serial no: SN-UNKNOWN. Pin was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										
321032	17 1	RIGHT MAIN LANDING GEAR FORWARD TRUNNION ATTACH PIN	RIGHT MAIN LANDING GEAR	6641424-1		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN. Removed serial no: SN-UNKNOWN. Pin was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										
321033	18 1	LEFT MAIN LANDING GEAR AFT TRUNNION ATTACH PIN	LEFT MAIN LANDING GEAR	6641424-8		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN Removed serial no: SN-UNKNOWN. Pin was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE,

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO	Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☒ Federal Aviation Administration ☐ Other (Specify) _____ and THIS STATEMENT IS TO CERTIFY THAT THE STATED MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURER'S INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PREPARED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.					
Work Inspected By	DANIEL COLLINS	Certificate No.	_____	Date	20-Aug-2017
Pertinent details of this maintenance are on file at _____ Under the above Work/Service Order Number as applicable.					

Maintenance Log	
Section	Page
3	4

**CESCOM****Maintenance Transaction Record**

MTR ID # 2759512

Page 5 of 7

CAMP Systems International

This Maintenance Report is To Be Used Solely For (Check One)

☒ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☐ APU
Serial No. _____**Aircraft Identification and Status**

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
321034	19 1	RIGHT MAIN LANDING GEAR AFT TRUNNION ATTACH PIN	RIGHT MAIN LANDING GEAR	6641424-8		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN. Removed serial no: SN-UNKNOWN. Pin was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										
323021	20 1	LEFT MAIN LANDING GEAR TRUNNION TO MAIN GEAR ACTUATOR ATTACH PIN	LEFT MAIN LANDING GEAR	6641623-1		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN. Removed serial no: SN-UNKNOWN. Pin was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										
323022	21 1	RIGHT MAIN LANDING GEAR TRUNNION TO MAIN GEAR ACTUATOR ATTACH PIN	RIGHT MAIN LANDING GEAR	6641623-1		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN. Removed serial no: SN-UNKNOWN. Pin was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										
321041	22 1	LEFT MAIN LANDING GEAR LOWER OLEO ATTACH BOLT	LEFT MAIN LANDING GEAR	NAS6212-23D		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN. Removed serial no: SN-UNKNOWN. Bolt was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE,

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076	
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO		Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the						
☒ Federal Aviation Administration ☐ Other (Specify) _____ and						
THIS STATEMENT IS TO CERTIFY THAT THE STATED MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURER'S INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.						
Work Inspected By	DANIEL COLLINS	Certificate No.	_____	Date	20-Aug-2017	
Pertinent details of this maintenance are on file at _____ under the above Work/Service Order Number as applicable.						

Maintenance Log	
Section	Page
3	5

**CESCOM****Maintenance Transaction Record**

MTR ID # 2759512

Page 6 of 7

CAMP Systems International

This Maintenance Report is To Be Used Solely For (Check One)

☒ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☐ APU
Serial No. _____**Aircraft Identification and Status**

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
321043	23 1	LEFT MAIN LANDING GEAR UPPER OLEO ATTACH BOLT	LEFT MAIN LANDING GEAR	NAS6312-39D		NSN	C	N 0 MTH 0 HRS		
Comments: Removed part no: UNKNOWN. Removed serial no: SN-UNKNOWN. Bolt was replaced in conjunction with trunnion replacement per the Cessna Model 560XL Maintenance Manual Chap 32-10-00, 32-10-01, and the Cessna Model 560XL Component Maintenance Manual Chap 32-10-01.										
324002	24 1	NOSE WHEEL ASSEMBLY	NOSE	3-1418-OPT3	9914069-3	9478	E	O 1 MTH 0 HRS		
Comments: Removed part no: 3-1418 Removed serial no: 3300. Installed wheel and tire assembly Overhauled by Aerospace Turbine Rotables Inc., CRS# NV2R045L, Wichita, KS. Serviced tire and installed wheel assembly per the Cessna Model 560XL Maintenance Manual Chap 32-41-01.										
324002	25 1	NOSE TIRE		031-613-8	9914070-1	7045S00467	C	N 0 MTH 0 HRS		
Comments: Removed part no: 031-613-8 Removed serial no: 6046S00342. New tire was supplied on wheel assembly listed above.										
A324006	26 2	NON DESTRUCTIVE TEST NOSE WHEEL ASSEMBLY : INSPECTION DOCUMENT 43	NOSE	3-1418-OPT3		9478				
Comments: NDT-Dye Penetrant Inspection was accomplished during overhaul of wheel Serial No 9478 by Aerospace Turbine Rotables Inc., CRS# NV2R045L, Wichita, KS. Refer to ATR Work Order WO108193.										
49APU1	27 1	APU		3800722-1	9912484-1	P-480	D	I		
Comments: Removed part no: 9912484-1 for shop visit-scheduled life limit items. Removed serial no: P386 with 4406.4 TTSN and 7743 TCSN. Installed Loaner APU which was inspected by Honeywell International Inc., CRS# ZN3R030M, Phoenix, AZ. APU installed and operational checked good per the Cessna Model 560XL Maintenance Manual Chap 49-10-00. Loaner APU has 2204 TTSN and 3025 TCSN. Loaner APU ECU reads 2204 cycles at this time. A placard was installed to "deduct 2202.4 Hours from hobbs, add 821 cycles to ECU reading". Current APU Hobbs reading is 4406.4.										

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE.

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO	Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☒ Federal Aviation Administration ☐ Other (Specify) _____ and					
THIS STATEMENT IS TO CERTIFY THAT THE ABOVE MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURER'S INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.					
Work Inspected By	DANIEL COLLINS	Certificate No.	_____	Date	20-Aug-2017
Pertinent details of this maintenance are on file at _____ under the above Work/Service Order Number as applicable.					

Maintenance Log

Section	Page
3	6

**CESCOM****Maintenance Transaction Record**

MTR ID # 2759512

Page 7 of 7

This Maintenance Report is To Be Used Solely For (Check One)

☒ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☐ APU
Serial No. _____

CAMP Systems International

Aircraft Identification and Status

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item -	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
D312002 312001A	28 2	REPLACE BATTERY LEFT HAND DIGITAL CLOCK : INSPECTION DOCUMENT 2	LEFT HAND	M877A5V		12845				
Comments: Replaced digital clock battery per the Cessna Model 560XL Maintenance Manual Chap 31-20-01. Operational checked good.										
D312002 312001A	29 2	REPLACE BATTERY RIGHT HAND DIGITAL CLOCK : INSPECTION DOCUMENT 2	RIGHT HAND	M877A5V		13798				
Comments: Replaced digital clock battery per the Cessna Model 560XL Maintenance Manual Chap 31-20-01. Operational checked good.										

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE,

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO	Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☒ Federal Aviation Administration ☐ Other (Specify) _____ and THIS STATEMENT IS TO CERTIFY THAT THE STATED MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURER'S INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PRESENTLY APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.					
Work Inspected By	DANIEL COLLINS	Certificate No.	_____	Date	20-Aug-2017
Pertinent details of this maintenance are on file at _____ under the above Work/Service Order Number as applicable.					

Maintenance Log

Section	Page
3	7

**CESCOM****Maintenance Transaction Record**

MTR ID # 2759626

Page 1 of 1

This Maintenance Report is To Be Used Solely For (Check One)

☒ Airframe
Entries☐ Eng. #1

Serial No. _____

☐ Eng. #2

Serial No. _____

☐ APU

Serial No. _____

Aircraft Identification and Status

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891	9662.4	8658.2	7075	6451	2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
SL560XL-29-05	1 3	HYDRAULIC POWER - ENGINE DRIVEN PUMP HYDRAULIC VERIFICATION, SERVICE LETTER MOC: NOT APPLICABLE Comments: Complied with SL560XL-29-05 engine driven pump hydraulic by visual inspection. Engine driven pump PN 9912062-7 is not installed on the aircraft. Engine driven pump installed on aircraft is PN 9912062-4. SL560XL-29-05 is not applicable.								

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE.

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO		Certificate No.	_____	Date 20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the ☒ Federal Aviation Administration ☐ Other (Specify) _____ and THIS STATEMENT IS TO CERTIFY THAT THE STATED MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURER'S INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PRESENTED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED. Work Inspected By DANIEL COLLINS _____ Certificate No. _____ Date 20-Aug-2017 Pertinent details of this maintenance are on file at _____ for the above Work/Service Order Number as applicable.					

Maintenance Log

Section	Page
4	1

**CESCOM**

MTR ID # 2759628 Replaces MTR ID # 2759523

Maintenance Transaction Record

Page 1 of 1

This Maintenance Report is To Be Used Solely For (Check One)

CAMP Systems International

☐ Airframe
Entries☐ Eng. #1
Serial No. _____☐ Eng. #2
Serial No. _____☒ APU
Serial No. 560XL-5326**Aircraft Identification and Status**

A/C Serial #	A/C Unit #	A/C Registration #	Date	City ID	Total A/C Hours	Total A/C Landings	Engine 1 Total Hrs	Engine 2 Total Hrs	Engine 1 Ttl Cycles	Engine 2 Ttl Cycles	APU Hrs	APU Events	Freon Hrs
560-5326		N503UP	20-Aug-2017	KMCO	9240.4	6891					2204	3,025	

Component Changes, Inspections, Service Bulletins, or Airworthiness Directives Accomplished

Item	Transaction No. Type	Item Name	Position	Part Number / Alternate Part	Mod Level	Part Serial	Removal Reason	Installed Part Status TSN/TSO/TSR	Material Costs	Man Hours
2759523	1 -	APU INSTALL						APUH		
Comments: This LOANER APU was installed on 560XL-5326, N503UP, at 9240.4 aircraft hours and 6891 landings. Unit was Inspected by Honeywell International Inc., CRS# ZN3R030M, Phoenix, AZ. APU installed and operational checked good per the Cessna Model 560XL Maintenance Manual Chap 49-10-00. Loaner APU has 2204 TTSN and 3025 TCSN. Loaner APU ECU reads 2204 cycles at this time. A placard was installed to "deduct 2202.4 Hours from hobbs, add 821 cycles to ECU reading". Current APU Hobbs reading is 4405.4.										
49-ECU DOWNLO	2 2	APU - DOWNLOAD DOCUMENT AND PROVIDE GAMA MAINTENANCE CONTROL WITH THE APU STARTS (ECU DOWNLOAD) READING. PROVIDE PICTURE SNAP SHOT OF THE APU ECU START COUNT READING.								
Comments: GAMA Aviation was provided with photo of ECU APU starts reading. Reading is 2204. Actual starts per LOANER APU 8130 lists 3025 starts.										
2759628	3 2	DOCUMENT 17		5-92-17				APUH		
Comments: Complied with Inspection Document 17 per the Cessna Model 560XL Maintenance Manual Chap 5-92-17 and the Honeywell RE100[XL] APU Maintenance Manual.										
2759628	4 2	DOCUMENT 18		5-92-18				APUH		
Comments: Complied with Inspection Document 18 per the Cessna Model 560XL Maintenance Manual Chap 5-92-18 and the Honeywell RE100[XL] APU Maintenance Manual. Serviced with BP2380 oil and leak checked good.										
2759628	5 2	DOCUMENT 30		5-92-30				APUH		
Comments: Complied with Inspection Document 30 per the Cessna Model 560XL Maintenance Manual Chap 5-92-30 and the Honeywell RE100[XL] APU Maintenance Manual.										

Trans. Type: 1 - Component, 2 - Inspection, 3 - SB, 4 - AD, -- Misc.

Removal Reasons: A - TIME EXPIRED, B - FAILURE, C - WORN, D - LOANER, E - SCHEDULING CONV, G - MOD/UPGRADE, K - SERVICE.

Installed Part Status: N - New, R - Repaired/Rebuilt, S - Serviceable, O - Overhauled

Repair Facility	TEXTRON AVIATION SERVICE - ORLANDO	Certified Repair Station Number	_____	Work Order No.	63076
Work Performed By	TEXTRON AVIATION SERVICE - ORLANDO	Certificate No.	_____	Date	20-Aug-2017
I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the					
☒ Federal Aviation Administration ☐ Other (Specify) _____ and					
THIS STATEMENT IS TO CERTIFY THAT THE ABOVE MAINTENANCE AND/OR INSPECTION WAS PERFORMED IAW THE GAMA AVIATION, LLC MAINTENANCE MANUAL, THE MANUFACTURER'S INSTRUCTIONS, AND MANUALS AND CURRENT REGULATIONS OF THE FAA. THE AIRCRAFT / ENGINE / ACCESSORY IDENTIFIED ABOVE IS PRESERVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.					
Work Inspected By	DANIEL COLLINS	Certificate No.	_____	Date	20-Aug-2017
Pertinent details of this maintenance are on file at _____ under the above Work/Service Order Number as applicable.					

Maintenance Log

Section	Page
12	1