



NTSB RECORD OF CONVERSATION

Kathryn Benhoff
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: May 10, 2018
Person Contacted: Kynan Spethman (General Manager at Northstar Jet)
NTSB Accident Number: WPR17LA046

The following is a summary of a telephone conversation with the above mentioned:

The General Manager of Northstar Jet reported that he received no reports from other customers during the period of the latest fueling (September 2, 2016) indicating that there were contaminants within the aviation fuel they distributed.

He further added that a fuel sample from the facility fuel sump is tested each morning before aircraft refueling. The fuel sample retained on the morning of September 2, 2016 was given a rating of "1A", meaning clear and bright and water-free.