

	Service Information No. SI-E4-010	Austro Engine GmbH Rudolf-Diesel-Strasse 11 2700 Wiener Neustadt PHONE: +43 2622 23000 FAX: +43 2622 23000-2711
---	--	---

SERVICE INFORMATION

No. SI-E4-010

1. BASIC INFORMATION

1.1. SUBJECT

Caution of foreign object ingestion during maintenance.

1.2. ENGINES AFFECTED

Type: E4
Model: E4, E4P
Serial Number(s): all

1.3. REASON

Austro Engine hereby cautions to secure the engine against foreign object ingestion during maintenance.

1.4. INFORMATION

On multiple occasions it has been observed that foreign object damage in the cylinder has led to engine failure.

Austro Engine strongly advises caution during maintenance on the engine installation.

- Always cover engine opening by appropriate means during maintenance.
- Always make sure that no foreign objects (e.g. residue of safety wire) enter into engine openings when parts or lines are removed.

2. REMARKS

NOTE: SI are used only:

- To distribute information from Austro Engine GmbH to our customers.
- To distribute applicable information/documents from our suppliers to our customers with additional information.

First Issue Date			Rev. No.	Revision Date				Page
16	Oct	2017	--	--	---	----		1-1