



RECORD OF CONVERSATION

Samantha Link
Aviation Accident Investigator
Western Pacific Region

Date: April 4, 2017
Person Contacted: Mr. Michael Marchand (Federal Aviation Administration)
NTSB Accident Number: WPR17LA092

Narrative:

During a telephone conversation with Mr. Michael Marchand from the Federal Aviation Administration he reported that, while on scene, he observed that the fuel tanks were intact and undamaged. He removed the fuel caps and observed that the right fuel tank was empty and a little fuel was observed in the left wing. In addition, the fuel selector within the cockpit was selected for the right wing fuel tank.

END.

Submitted by: Samantha Link